

Alert number

SR/03823/25Notifying country **Germany**Product category **Motor vehicles**Type **Consumer**Product **Passenger car**Name **X5, X6, X7, 7, 8 (Coupe, Cabrio, Gran Coupe), M340**Brand **Bmw**EC-type approval/model **G05, G06, G07, G12, G14, G15, G16, G20 (US version) equipped with B58 engine**Production dates **20.03.2018 to 11.02.2025**Company recall code **0012590600**Product description **Passenger car.****Fire**

Risk type	
Risk description	The engine starter's electrical contacts may overheat and cause the vehicle to start improperly. Continued starting attempts can intensify the overheating and ignite surrounding components, potentially leading to a vehicle fire while driving or shortly after parking.
Legal provisions (at EU level) and European standards against which the product was tested and did not comply	The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles.
Country of origin	Germany
Measures taken by economic operators	Recall of the product from end users Manufacturer
Recall website	- <a href="https://www.bmw.de/de/topics/service-zubehoer/bmw-service/rueckrufe.html"><u>https://www.bmw.de/de/topics/service-zubehoer/bmw-service/rueckrufe.html</u></a>
Products were found and measures were taken also in	Bulgaria Denmark Estonia France Croatia Hungary Luxembourg Norway Portugal Sweden Slovenia